

Digitized by the Internet Archive  
in 2015

FIG. 4.



FIG. 2.




FIG. 3.




FIG. 1.




FIG. 9.




FIG. 7.




FIG. 8.




FIG. 6.



FIG. 5.




FIGURE 1.





FIGURE 2




*The enrolled drawing is not colored*

*Drawn on Stone by Maury & Sons*



Examples










FIG. 2.






The omitted drawing is colored.





*The enrolled drawing is colored.*






*The enrolled drawing is colored.*



A D 1824 JAN 19. N° 4893.  
BROADMEADOW'S SPECIFICATION.



*The enrolled drawing is colored.*

Drawn and Engraved by M. J. & Co.



A.D 1854, Jan 24 N<sup>o</sup> 1895  
BEWLEY'S SPECIFICATION

4 SHEETS

FIG. 4.



*The curved drawing is added*

FIG 5






FIG 1




FIG 2



The enrolled drawing is referred to

Drawings made by Mills & Co.





A B C D E F G H I J K L M N O P Q R S T U V W X Y Z.

The Valve is nearly ready  
Start the Engine  
The Valve is quite ready  
The Valve is off.




FIG. 17.




FIG. 6.




FIG. 7.




FIG. 3.




FIG. 2.




FIG. 11. B.




FIG. 1. B.




FIG. 5.



FIG. 4.




FIG. 8.




FIG. 9.




FIG. 10.




FIG. 11.




FIG. 12.




FIG. 13.




FIG. 14.




FIG. 15.

The enrolled drawing is partly colored.











